



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80114

## Inspection Report

Project Name: Lot 2 - 3504 Brighton Pk Cir ~ COBI Bldg 16  
Address: Lot 2 - 3504 Brighton Park Circle ~ COBI, Belle Isle, Orange  
County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1700010.0000-0115-03  
Scope of Inspection: Brighton Park - Underground Plumbing Inspection  
Inspection Type: See Scope

Date: 04/07/2017 Any pm  
Permit No: 2017-04-007  
Lot No.:  
Contact: Gary Preston at (407) 590-4329

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498