



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79957

Inspection Report

Project Name: Lot 48 3569 Brighton Park Cir ~ COBI TH

Date: 04/05/2017 Any any

Address: Lot 48 3569 Brighton Park Cir ~ COBI TH, Belle Isle, Orange County, FL

Permit No: 2017-01-067

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700024.0000-0115-01

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW Bldg 12 building permit app for new townhome

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927