



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79959

Inspection Report

Project Name: Lot 50 3577 Brighton Park Cir ~ COBI TH

Date: 04/05/2017 Any any

Address: Lot 50 3577 Brighton Park Cir ~ COBI TH, Belle Isle, Orange
County, FL

Permit No: 2017-01-069

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700026.0000-0115-01

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW Bldg 12 building permit app for new townhome

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927