



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80249

Inspection Report

Project Name: Lot 70 3741 Brighton Park Circle ~ COBI townhouse

Date: 04/13/2017 Any am

Address: Lot 70 3741 Brighton Park Circle ~ COBI, Belle Isle, Orange
County, FL

Permit No: 2017-03-052

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700103.0000-0115-01

Contact: Dale Baker at Verbal

Scope of Inspection: Building 4 ~ REVIEW building permit app & plans for new townhouse

Inspection Type: **See Scope**

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927