



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 81082

Inspection Report

Project Name: Lot 73 3753 Brighton Park Circle ~ COBI TH
Address: Lot 73 3753 Brighton Park Circle ~ COBI, Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700106.0000-0115-03

Date: 04/26/2017 Any any
Permit No: 2017-04-089
Lot No.:
Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW plumbing permit app for new townhouse

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927