



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 81048

## Inspection Report

Project Name: Lot 76 3765 Brighton Park Circle ~ COBI

Date: 04/26/2017 Any any

Address: Lot 76 3765 Brighton Park Circle ~ COBI, Belle Isle, Orange  
County, FL

Permit No: 2017-04-085

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700110.0000-0115-02

Contact: Susan Manchester at 407 581  
8161

Scope of Inspection: REVIEW electrical permit app for townhome

Inspection Type: See Scope

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927