



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80892

Inspection Report

Project Name: Lot 81 - 3815 Brighton Park Circle ~ COBI

Date: 04/21/2017 Any any

Address: Lot 81 - 3815 Brighton Park Circle ~ COBI, Belle Isle, Orange
County, FL

Permit No: 2017-01-028

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600524.0000-0115-03

Contact: Gary Preston at (407) 590-4329

Scope of Inspection: Brighton Park - Prepower Inspection for HVAC, all outlets, switches and fixtures.

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564