



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80869

## Inspection Report

Project Name: Lot 82 - 3819 Brighton Park Circle ~ COBI

Date: 04/20/2017 Any pm

Address: Lot 82 - 3819 Brighton Park Circle ~ COBI, Belle Isle, Orange  
County, FL

Permit No: 2017-10-022

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600525.0000-0115-01

Contact: Gary Preston at (407) 590-4329

Scope of Inspection: Brighton Park - Driveway / Sidewalk Apron Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564