



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40333

Inspection Report

Project Name: 1401 Horizon Court ~ COBI

Date: 08/05/2014 Early am

Address: 1401 Horizon Court ~ COBI ,Belle Isle, Orange

Permit No.: 2014-07-008

Client: ^{County, FL}
City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400337.0000

Contact: Clyde Mid FL Pools at 407 342 3211

Scope of Inspection: Underground electrical inspection for pool

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362