



# UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40995

## Inspection Report

Project Name: 1508 Conway Isle Circle - COBI  
Address: 1508 Conway Isle Circle - COBI ,Belle Isle, Orange  
County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1400218.0000

Date: 08/20/2014 Any am  
Permit No.: 2014-04-048  
Lot No.:  
Contact: David Loy at 407 620 5194

Scope of Inspection: In progress window/door install inspection

**Inspection Type:** See Scope

**Disposition of Inspection:** Pass

### Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362