



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40993

Inspection Report

Project Name: 1508 Conway Isle Circle - COBI
Address: 1508 Conway Isle Circle - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400218.0000

Date: 08/20/2014 Any am
Permit No.: 2014-08-004
Lot No.:
Contact: David Loy at 407 620 5194

Scope of Inspection: Roof dry-in/ flashing inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362