



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40244

Inspection Report

Project Name: 2847 Alsace Court ~ COBI
Address: 2847 Alsace Court ~ COBI ,Belle Isle, Orange
Client: ^{County, FL} City of Belle Isle
ProjectNo.: 0115.1400133.0000

Date: 07/31/2014 Any any
Permit No.: 2014-04-029
Lot No.:
Contact: Brett at 321-704-0958

Scope of Inspection: Exterior Wall Sheathing inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362