

UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maggie Boulevard Orlando, FL 32811

Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40467

Inspection Report

08/11/2014 Any any Project Name: 3745 Rothbury Drive ~ COBI Date: Address: 3745 Rothbury Drive ~ COBI ,Belle Isle, Orange Permit No.: 2014-01-035 County FL City of Belle Isle Client: Lot No .: 0115.1400050.0000 Phil Sutherland at Email ProjectNo.: Contact: Scope of Inspection: Investigate electrical work (camera) installed without a permit; if evidence is present, take pictures & send to office for Code Enforcement follow-up. **Inspection Type:** See Scope **Disposition of Inspection:** Complete

Comments:

08/11/2014 found no work going on at this time.

xis A Colon

Luis Colon

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362