

UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maggie Boulevard Orlando, FL 32811

Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40630

Inspection Report

Project Name: 3913 Quando Drive ~ COBI	Date: 08/13/2014 Any any
Address: 3913 Quando Drive ~ COBI ,Belle Isle, Orange	Permit No.: 2014-06-034
Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1400326.0000	Contact: Ashley Grow at 407 295 7403
Scope of Inspection: Roof in progress inspection	
Inspection Type: See Scope	
Disposition of Inspection: Pass	
Comments:	

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362

sis A Colon