



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40927

Inspection Report

Project Name: 3921 Isle Vista Avenue - COBI
Address: 3921 Isle Vista Avenue - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400077.0000

Date: 08/20/2014 Any any
Permit No.: 2014-08-072
Lot No.:
Contact: Lisa at 407-718-8618

Scope of Inspection: REVIEW: Plumbing Permit for Irrigation System

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

08/20/2014 approved

Angel Perez

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Angel Perez, BN 5240