



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.41018

Inspection Report

Project Name: 4226 Bell Tower Ct ~ COBI

Date: 08/20/2014 Any am

Address: 4226 Bell Tower Ct ~ COBI ,Belle Isle, Orange

Permit No.: 2014-08-006

Client: ^{County, FL}
City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400408.0000

Contact: Brite Top Roofing at 407 895 1551

Scope of Inspection: In-progress roof inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

08/20/2014 dry-in only

Luis Colon

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362