



**UNIVERSAL ENGINEERING SCIENCES, INC.**

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

**Work Order No.40223**

**Inspection Report**

Project Name: 5001 St. Marie Avenue - COBI  
Address: 5001 St. Marie Avenue - COBI ,Belle Isle, Orange  
County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1400390.0000

Date: 08/01/2014 Any any  
Permit No.: 2014-07-055  
Lot No.:  
Contact: Dorothy Hall at 407 851 0680

Scope of Inspection: In progress roof inspection

**Inspection Type: See Scope**

**Disposition of Inspection: Pass**

**Comments:**

08/02/2014 deck nailing / dry-in, flashing also passed

Luis Colon

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362