



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.41179

Inspection Report

Project Name: 5138 Oak Island Road - COBI
Address: 5138 Oak Island Road - COBI ,Belle Isle, Orange
Client: ^{County, FL} City of Belle Isle
ProjectNo.: 0115.1300215.0000

Date: 08/25/2014 Any any
Permit No.: 2014-08-077
Lot No.:
Contact: Collina Gast at 407-581-8161

Scope of Inspection: REVIEW building permit app (rec'd zoning approval)

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Angel Perez, BN 5240