



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.41141

Inspection Report

Project Name: 5256 Jade Circle~ COBI

Date: 08/22/2014 Any any

Address: 5256 Jade Circle~ COBI ,Belle Isle, Orange County,

Permit No.: 2014-08-061

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400410.0000

Contact: Catherine Pagliazzo at 407 849 7663

Scope of Inspection: FINAL roof inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

08/25/2014 Pass via phone from Angel Perez.

Susan Manchester

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Angel Perez, BN 5240