



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40571

Inspection Report

Project Name: 5385 Jade Circle - COBI
Address: 5385 Jade Circle - COBI ,Belle Isle, Orange County,
Client: City of Belle Isle
ProjectNo.: 0115.1400196.0000

Date: 08/11/2014 Any any
Permit No.: 2014-04-032
Lot No.:
Contact: Troy at 321 303 0650

Scope of Inspection: Footer inspection for community wall

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362