



# UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40981

## Inspection Report

Project Name: 6427 St. Partin Place ~ COBI  
Address: 6427 St. Partin Place ~ COBI ,Belle Isle, Orange  
County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1400412.0000

Date: 08/20/2014 Any any  
Permit No.: 2014-08-067  
Lot No.:  
Contact: Carrie Laubenheimer at 407 291 9364

Scope of Inspection: In-progress plumbing inspection (re-pipe) Final inspection will be needed when fixtures installed.

**Inspection Type:** See Scope

**Disposition of Inspection:** Pass

**Comments:**

08/20/2014 plumbing in progress, fixtures and valves not installed, repipe good.

Luis Colon

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362