



**UNIVERSAL ENGINEERING SCIENCES, INC.**

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

**Work Order No.40722**

**Inspection Report**

Project Name: 6927 Seminole Drive - COBI  
Address: 6927 Seminole Drive - COBI ,Belle Isle, Orange  
County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1400391.0000

Date: 08/14/2014 Any am  
Permit No.: 2014-07-056  
Lot No.:  
Contact: Robert Batson at 407-423-7570

Scope of Inspection: In-progress roof inspection

**Inspection Type: See Scope**

**Disposition of Inspection: Pass**

**Comments:**

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362