



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40272

Inspection Report

Project Name: 7125 Conway Circle - COBI
Address: 7125 Conway Circle - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400017.0000

Date: 08/05/2014 Any any
Permit No.: 2014-02-029
Lot No.:
Contact: Christina at 386 957 4005

Scope of Inspection: FINAL roof inspection (completed 7 months ago)

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362