



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.40214

Inspection Report

Project Name: 7244 Conway Circle ~ COBI
Address: 7244 Conway Circle ~ COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400352.0000

Date: 07/31/2014 Any any
Permit No.: 2014-07-023
Lot No.:
Contact: Renier at 321 229 8657

Scope of Inspection: Framing inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362