



**UNIVERSAL ENGINEERING SCIENCES, INC.**

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

**Work Order No.40215**

**Inspection Report**

Project Name: 7244 Conway Circle ~ COBI  
Address: 7244 Conway Circle ~ COBI ,Belle Isle, Orange  
County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1400352.0000

Date: 07/31/2014 Any any  
Permit No.: 2014-07-053  
Lot No.:  
Contact: Renier at 321 229 8657

Scope of Inspection: In progress roof inspection

**Inspection Type: See Scope**

**Disposition of Inspection: Pass**

**Comments:**

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362