



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55879

## Inspection Report

Project Name: 1200 Waltham Avenue ~ COBI

Date: 08/19/2015 Late am

Address: 1200 Waltham Avenue ~ COBI ,Belle Isle, Orange County,  
FL

Permit No: 2015-07-042

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501011.0000

Contact: Adam Ruschak at 321-652-2101

Scope of Inspection: Mechanical Rough-in Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489