



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55604

Inspection Report

Project Name: 1518 Swann Avenue ~ COBI
Address: 1518 Swann Avenue ~ COBI ,Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1500929.0000

Date: 08/13/2015 Any any
Permit No: 2015-07-009
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW electrical app for porch that was enclosed in without permit several years ago

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/12/2015	Per Jay - pass - note permit that all outlets are to be inspected to insure that they are tamper resistance and arc-fault protected.	Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: John Connell, BN3221