



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55758

## Inspection Report

Project Name: 1518 Swann Avenue ~ COBI

Address: 1518 Swann Avenue ~ COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1500929.0000

Scope of Inspection: Final Building Inspection

Inspection Type: See Scope

Date: 08/17/2015 Late pm

Permit No: 2015-07-008

Lot No.:

Contact: Katharine Miller at 407-574-0342

Disposition of Inspection: Pass

### Comments:

| <u>Task Date</u> | <u>Task Note</u>  | <u>User Name</u> |
|------------------|---|------------------|
| 08/17/2015       | Inspection results are based on an engineering report. The work was done without a permit. The homeowner put their house on the market and the title search found that the alteration was made without permits. | Ralph Jones      |

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Ralph Jones, BN1437