



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 56251

Inspection Report

Project Name: 1617 Idaho Avenue ~ COBI

Address: 1617 Idaho Avenue ~ COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1300676.0000

Scope of Inspection: Final Roof Inspection

Inspection Type: See Scope

Date: 08/25/2015 Any any

Permit No: 2015-08-014

Lot No.:

Contact: Nicole at 407-275-9444

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/25/2015	flashing which meets code required at rear of house for end of cable	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362