3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 54797

Inspection Report

		Wind Harbor Road ~ COBI	Date:	07/31/2015 Any any
	1645 Wind FL	d Harbor Road ~ COBI ,Belle Isle, Orange County,	Permit No:	2015-07-040
Client:	ient: City of Belle Isle		Lot No.:	
ProjectNo.:	0115.	1501010.0000	Contact:	Russell Sweeney at 407-896-3136
Scope of Inspection:		Final plumbing inspection		_
Inspection Type:		See Scope		
Disposition of Inspection: Pass				

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362