



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55914

Inspection Report

Project Name: 1791 Pam Circle ~ COBI

Date: 08/24/2015 Any am

Address: 1791 Pam Circle ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-07-029

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500969.0000

Contact: Caytlin Hill at 407-532-8000

Scope of Inspection: Final Mechanical Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362