



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 56066

## Inspection Report

Project Name: 1924 Hoffner Avenue ~ COBI  
Address: 1924 Hoffner Avenue ~ COBI ,Belle Isle, Orange County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1501125.0000

Date: 08/21/2015 Any any  
Permit No: 2015-08-043  
Lot No.:  
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW app for mechanical permit one 4-ton changeout

Inspection Type: See Scope

Disposition of Inspection: Complete

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/21/2015	Approved	John Connell

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: John Connell, BN3221