



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55750

Inspection Report

Project Name: 2323 McCoy Road ~ COBI~ Palm Square Condos (multi-family)

Date: 08/17/2015 Any any

Address: 2323 McCoy Road ~ COBI~ Palm Square Condos (multi-, Belle Isle, Orange County, FL

Permit No: 2015-12-052

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400403.0001

Contact: Sunia Piedmont at 407-947-4968

Scope of Inspection: Bldg. 7, Unit 716 - Framing Reinspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/17/2015	framing subject to verification of through penetration firestop assemblies for plumbing DWV and fireblocking at non-tenant seperation walls at furred cielings. OK to insulate	Ralph Jones

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Ralph Jones, BN1437