



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 56307

## Inspection Report

Project Name: 2323 McCoy Road ~ COBI~ Palm Square Condos (multi-family)

Date: 08/26/2015 Any any

Address: 2323 McCoy Road ~ COBI~ Palm Square Condos (multi-, Belle Isle, Orange County, FL

Permit No: 2015-08-047

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.0100403.0002

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: Building 7 unit 719 - REVIEW app for plumbing for condo rehab

Inspection Type: **See Scope**

Disposition of Inspection: Complete

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/26/2015	Approved	John Connell

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: John Connell, BN3221