

## 3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

## Work Order No. 55486

## **Inspection Report**

Inspection Type:		See Scope		
Scope of Inspection:		REVIEW mechanical app - compressor change out only		
ProjectNo.: 0115.1		1500164.0000	Contact:	Susan Manchester at 407 587 8161
Client:	City of Bel	le Isle	Lot No.:	
Address:	2424 Hoffner Avenue ~ COBI ,Belle Isle, Orange County, FL		Permit No:	2015-08-026
Project Name: 2424 Hoffner Avenue ~ COBI			Date:	08/11/2015 Any any

## Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector:

John Connell, BN3221

l'ece