



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55676

## Inspection Report

Project Name: 2915 Nela Avenue ~ COBI

Date: 08/14/2015 Any any

Address: 2915 Nela Avenue ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-08-012

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500800.0000

Contact: Robert Byrd at 407-405-5753

Scope of Inspection: Rough Electrical Reinspection for boat dock

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Thomas Romboli, BN 3493