



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55484

Inspection Report

Project Name: 3308 Flowertree Road ~ COBI

Date: 08/12/2015 Any any

Address: 3308 Flowertree Road ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-07-019

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500951.0000

Contact: Britney Hastings at 407-333-2665

Scope of Inspection: Final Mechanical Inspection

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/12/2015	access required for inspection	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362