



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 56067

Inspection Report

Project Name: 3950 Isle Vista Ave - COBI	Date: 08/21/2015 Any any
Address: 3950 Isle Vista Ave ,Belle Isle, Orange County, FL	Permit No: 2015-08-044
Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1500740.0000	Contact: Terry Warren at 407-855-6226
Scope of Inspection: REVIEW gas app. to install 60 gallon tank and run gas line to two firebowls.	
Inspection Type: See Scope	

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/21/2015	Disapproved 1. Show type of gas piping 2. Show the pressure drop 3. Show the BTU's of the appliances 4. Provide gas drawing to include pipe sizes and length of runs	John Connell

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: John Connell, BN3221