



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55487

## Inspection Report

Project Name: 4344 Kandra Court - COBI

Address: 4344 Kandra Court - COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1300459.0000

Scope of Inspection: Final plumbing inspection, re-pipe final.

Inspection Type: See Scope

Date: 08/11/2015 Any any

Permit No: 2015-06-037

Lot No.:

Contact: Luis at 407 581 8161

Disposition of Inspection: Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/11/2015	final for re-pipe	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362