



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55098

Inspection Report

Project Name: 5018 Monet Avenue ~ COBI

Date: 08/03/2015 Any am

Address: 5018 Monet Avenue ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-12-025

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400557.0000

Contact: Jerry Miller at 407 509-0370

Scope of Inspection: Final building inspection

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Thomas Romboli, BN 3493