



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55357

Inspection Report

Project Name: 5019 Saint Germaine Avenue ~ COBI

Address: 5019 Saint Germaine Avenue ~ COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1501080.0000

Scope of Inspection: REVIEW app for re-pipe

Inspection Type: See Scope

Date: 08/07/2015 Any any

Permit No: 2015-08-024

Lot No.:

Contact: Susan Manchester at 407 581 8161

Disposition of Inspection: Complete

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/07/2015	approved	John Connell

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: John Connell, BN3221