



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55417

Inspection Report

Project Name: 5019 Saint Germaine Avenue ~ COBI

Date: 08/11/2015 Any am

Address: 5019 Saint Germaine Avenue ~ COBI ,Belle Isle, Orange
County, FL

Permit No: 2015-08-024

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501080.0000

Contact: Myrna Steele at 407-898-3538

Scope of Inspection: Final Plumbing Inspection

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/11/2015	water heater relief line shall not be reduced, not to code, hammer arrestor for dishwasher required	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362