3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55623

Inspection Report

Project Name: 5019 Saint Germaine Avenue ~ COBI	Date:	08/13/2015 Any any
Address: 5019 Saint Germaine Avenue ~ COBI ,Belle Isle, Orange County, FL	Permit No:	2015-08-024
Client: City of Belle Isle	Lot No.:	-
ProjectNo.: 0115.1501080.0000	Contact:	Myrna Steele at 407-898-3538
Scope of Inspection: Final Plumbing Inspection		
Inspection Type: See Scope		
Disposition of Inspection: Pass		
Comments:		

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362