

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55477

## **Inspection Report**

Project Name: 5026 Saint Marie Avenue ~ COBI

Address: 5026 Saint Marie Avenue ~ COBI ,Belle Isle, Orange County,
FL

Date: 08/12/2015 Any any
Permit No: 2015-07-054

Client: City of Belle Isle Lot No.:

ProjectNo.: 0115.1501038.0000 Contact: Susan Manchester at 407 581

8161

Scope of Inspection: REVIEW app for 12 x 25 storage building - zoning approved

Inspection Type: See Scope

**Disposition of Inspection:** Pass

**Comments:** 

 Task Date
 Task Note
 User Name

 08/13/2015
 Approved
 John Connell

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: John Connell, BN3221

lece