



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55920

## Inspection Report

Project Name: 5120 Conway Road ~ COBI commercial

Address: 5120 Conway Road ~ COBI commercial ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1501094.0000

Scope of Inspection: REVIEW app for bfulding for sign

Inspection Type: See Scope

Date: 08/19/2015 Any any

Permit No: 2015-08-033

Lot No.:

Contact: Susan Manchester at 407 581 8161

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/19/2015	Disapproved 1. The plans need to be signed and sealed and show the wind load information per FBC 1609	John Connell

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: John Connell, BN3221