



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55953

Inspection Report

Project Name: 5120 Saint Germaine Avenue ~ COBI	Date: 08/20/2015 Any any
Address: 5120 Saint Germaine Avenue ~ COBI ,Belle Isle, Orange County, FL	Permit No: 2015-08-038
Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1501115.0000	Contact: Byron Gauthier at 407 615 4418
Scope of Inspection: Final electrical inspection for interior panel change-out	
Inspection Type: See Scope	

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/20/2015	NEC 408.4 requires panel circuit directory labeled.	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362