



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 56073

Inspection Report


Project Name:	5138 Oak Island Road - COBI	Date:	08/24/2015 Any any
Address:	5138 Oak Island Road - COBI ,Belle Isle, Orange County, FL	Permit No:	2015-04-019
Client:	City of Belle Isle	Lot No.:	
ProjectNo.:	0115.1300215.0000	Contact:	Marty Osteen at 386-736-4220
Scope of Inspection:	2nd Plumbing Rough Inspection		
Inspection Type:	See Scope		

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362



Luis A. Colon