



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 56052

## Inspection Report

Project Name: 5210 Oak Island Road ~ COBI  
Address: 5210 Oak Island Road ~ COBI ,Belle Isle, Orange County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1500551.0000

Date: 08/21/2015 Any any  
Permit No: 2015-04-074  
Lot No.:  
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW new requested info for building app

Inspection Type: See Scope

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/21/2015	The re-submittal was partial - The items they addressed was acknowledged and a new plan review report was generated.	Ralph Jones

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Ralph Jones, BN1437