3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55015

Inspection Report

Project Name: 5224 Chiswick Circle - COBI			Date:	07/31/2015 Any am
Address: 5224 Chiswick Circle - COBI ,Belle Isle, Orange County, FL			Permit No:	2015-06-035
Client: City of Belle Isle		Lot No.:		
ProjectNo.: 0115.1300633.0000		Contact:	Tad Price at 407-970-6636	
Scope of Inspection:		Footing/foundation inspection for screen enclosure		
Inspection Type:		See Scope		
	·	<u> </u>	•	_

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

xis A Colon

Inspector: Luis Colon, BN3362