



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55076

Inspection Report

Project Name: 5362 Hawford Circle - COBI

Date: 07/31/2015 Any any

Address: 5362 Hawford Circle - COBI ,Belle Isle, Orange County, FL

Permit No: 2015-07-053

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400056.0000

Contact: Paul Schick at 407-310-6484

Scope of Inspection: Roof in-progress inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362